Amendments to the specification

Please replace paragraph **[0004]** with the following amended paragraph:

[0004] However, the through holes 910 render a layout of circuit paths in the PCB 91 inconvenient. Furthermore, the frame 98a has a configuration occupying relatively large real estate on the PCB 91. US Pat. Nos. ~~6,466,446~~ 6,466,443, 6,449,157 and 5,854,738 each have similar shortcoming as stated above.

PAGE 3/13 * RCVD AT 5/22/2006 9:43:13 PM [Eastern Daylight Time] * SVR:USPTO-EFXRF-3/18 * DNIS:2738300 * CSID:408 919 8353 * DURATION (mm-ss):03-36